

 <p><b>Namibia Civil Aviation Authority</b> Air Navigation Service Aeronautical Information Management</p>	<h2>Daily NOTAM Bulletin</h2>	Effective Date: 15 Sep 2018
	AIM SSI -001 F -03	Version 2

### AERONAUTICAL INFORMATION SERVICES

Tel: +264-61-702087/83/80  
 Fax: +264-61-702088  
 Telex: 50-908) 811/2 WK  
 E-mail: [aisc@dca.com.na](mailto:aisc@dca.com.na)  
 Website: [www.dca.com.na](http://www.dca.com.na)

NAMIBIA CIVIL AVIATION AUTHORITY  
 Private Bag 12003  
 Ausspannplatz  
 Windhoek  
 NAMIBIA

**DAILY NOTAM BULLETIN** 25<sup>th</sup> May 2019  
<http://www.ncaa.com.na/ans-notam.htm>

Enquiries: AISO

Our Ref: NTMS 2017

FYHO	C0068/18	1805030946	PERM	PILOTS AND OPERATORS ARE ADVISED THAT UNEXPECTED WIND SHEAR AND TURBULENCE HAVE BEEN REPORTED WHEN APPROACHING RWY 18/36, ON SHORT FINAL AND DURING FLARE. DUE TO SOFT (IRREGULAR) RWY SURFACE AT HOANIB, IT IS RECOMMENDED THAT NO ACFT NOT SUITABLY EQUIPPED FOR SOFT SURFACES BE OPERATED INTO THE AIRSTRIP. PILOTS TO MAKE INQUIRIES ABOUT OPERATING CONDITIONS AT: +264 61 274 200.
FYKM	B0037/19	1903141730	1906131500 EST	TAF ISSUED BY MET SERVICE PROVIDER FOR FYMP IS MEANT FOR FYKM (KATIMA MULILO) NOT OKAMAPU.
FYKM	B0062/19	1904041402	1907031500	MET EQUIPMENT UNCALIBRATED DUE TO MET SERVICE PROVIDER NOT MEET ANNEX 3 REQUIREMENTS.
FYKM	B0066/19	1904071301	1907031500	MET DATA DISPLAY IN THE TOWER U/S. MET INFO IS OBTAINED FROM FYKM MET OFFICE.
FYKM	B0074/19	1905240600	1908231630	DUE TO OBSC VIS OF THE RWY FM THE ATC TWR BY TALL GRASS, NO LDG OR TKOF CLEARANCES WILL BE ISSUED BY ATC. ACFT WILL BE INSTRUCTED TO LAND/TKOF AT THEIR OWN DISCRETION.
FYKT	B0026/19	1902201250	PERM	HAND AMEND NAMIBIAN AIP FYKT AD 2.2(5) AD ADMIN DELETE ATC TEL AND FAX NUMBERS CHANGE AFS: NIL
FYKT	B0027/19	1902201252	PERM	HAND AMEND NAMIBIAN AIP FYKT AD 2.3 AD OPR HRS AMEND 5 TO READ ATS REPORTING OFFICE: NIL AMEND 6 TO READ MET BRIEFING OFFICE : 0300-1800
FYKT	B0028/19	1902201255	PERM	HAND AMEND NAMIBIAN AIP FYKT AD 2.11 MET INFO AMEND 2 TO READ HOS:0300-1800 MET OFFICE OUTSIDE HOURS: WINDHOEK TEL +26462540059 AMEND 9 TO READ ATS UNITS PROVIDED WITH SERVICE: FYWH ACC

1

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.



**Namibia Civil Aviation Authority**  
**Air Navigation Service**  
**Aeronautical Information**  
**Management**

## Daily NOTAM Bulletin

Effective Date:  
15 Sep 2018

AIM SSI -001 F -03

Version 2

FYKT	B0038/19	1903141737	1906131500 EST	MET EQUIPMENT UNCALIBRATED DUE TO MET SERVICE PROVIDER NOT MEET ANNEX 3 REQUIREMENTS.
FYLZ	B0035/19	1903141627	1906131500 EST	MET EQUIPMENT UNCALIBRATED DUE TO MET SERVICE PROVIDER NOT MEET ANNEX 3 REQUIREMENTS.
FYLZ	B0056/19	1903310726	1906301300	TWR HOURS OF OPS/SERVICE MON-FRI 0600-1000 AND 1100-1500 SAT: NIL SUN: 0700-1300
FYLZ	B0058/19	1904011300	1905311500	FIRE FIGHTING AVBL BUT NIL RESCUE SERVICES
FYOA	B0044/18	1804260800	PERM	THR RWY 08 DISPLACED BY 163M TOTAL RWY LENGTH IS 2824M. DECLARED DISTANCE NOT DETERMINED.
FYOA	B0045/18	1804260751	PERM	RNP RWY 08 DUE DTHR BARO VNAV NOT AUTHORISED X LNAV MDA (OCH) INCREASED TO 4100(501)FT
FYOA	B0122/18	1811271533	PERM	HAND AMEND NAMIBIAN AIP FYOA AD 2-11 AND 2-13 DELETE ONDANGWA TMA A C FL145 - 5500
FYOA	B0036/19	1903141640	1906131500	MET EQUIPMENT UNCALIBRATED DUE TO MET SERVICE PROVIDER NOT MEET ANNEX 3 REQUIREMENTS.
FYOA	B0050/19	1903251748	1906302359	AERODROME HOURS OF OPS/SERVICE  SUNDAY TO FRIDAY:0400 TO 1730 SATURDAY: 0400 TO 1200 AIRPORT AFTERS HOURS OPERATION REQUEST MR. EN SHOOMBE CELL:+264811441633
FYOA	B0051/19	1903280500	1906281730	MON - FRI 0500 – 1730 SAT 0500 - 1200 SUN 0500 - 1000 AND 1300 - 1730
FYOA	B0061/19	1904030934	1907032359	ANNUAL WGS-84 SURVEY NOT COMPLETED. ALL AERODROME DATA NOT VALIDATED.
FYOA	A0097/19	1902251744	1906302359	RWY08/26 LENGTH 2824M THR RWY08 DISPLACED BY 162M RWY08/26 WIDTH 45M RWY08/26 PCN 48/F/B/X/T TWY PCN 12/F/D/Y/U APRON PCN 12/F/D/Y/U
FYOA	B0070/19	1904271058	1907262359	U/S AREAS ON THE APRON MARKED WITH REFLECTIVE CONES.
FYOG	B0084/18	1808090345	PERM	HAND AMEND NAMIBIAN AIP FYOG AD2-11 DATED 10 NOV 2016 COMMUNICATION FAILURE PROCEDURE, REPLACE OG201 WITH OG202.

2

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.



**Namibia Civil Aviation Authority**  
**Air Navigation Service**  
**Aeronautical Information**  
**Management**

## Daily NOTAM Bulletin

Effective Date:  
15 Sep 2018

AIM SSI -001 F -03

Version 2

FYOU	B0085/19	1905220400	1905291600	WIP GRASS CUTING ON RWY 08/26 AND RWY 17/35. PILOTS TO EXERCISE CAUTION
FYRN	C0098/18	1806250912	PERM	NEW RHINO CAMP DIMENSIONS ARE AS FOLLOWS : COORDINATES 200211S0135035E RWY DESIGNATORS RWY09/27 DISPLACED TO A POINT OF 100M FM THE INITIAL POINT, THE FOLLOWING DECLARED DISTANCES IN METERS ARE AVBL FOR RWY09 TODA:1400M LDA:1300 DISTANCE IN METERS FOR RWY27 TODA:1400M LDA:1300M FOR FURTHER INFOR CONTACT 061-25573
FYSM	C0087/19	1905280400	1905281600	RWY17/35 CLSD DUE TO WIP.
FYSM	C0088/19	1905270400	1905281600	RWY06/24 CLSD DUE TO WIP.
FYSM	C0089/19	1905290400	1905291600	TWY CLSD DUE TO WIP.
FYWB	A0065/19	1903141623	1906131500 EST	MET EQUIPMENT UNCALIBRATED DUE TO MET SERVICE PROVIDER NOT MEET ANNEX 3 REQUIREMENTS.
FYWB	A0184/19	1905080800	1908080800	PILOTS TO IGNORE TRANSITION LEVEL 50 ON FYWB ATIS.FOR CORRECT TRANSITION LEVEL CONTACT FYWB ATC.
FYWB	A0099/19	1903290600	1906291500	ANNUAL WGS-84 SURVEY NOT COMPLETED. ALL AERODROME DATA NOT VALIDATED.
FYWB	A0113/19	1904040405	1906302359	FYWB ILS/DME WBI FREQ109.3MHZ OPR BUT NO GND CK AWAITING FLT CK.
FYWB	A0170/19	1905010600	1905311500	AVGAS FUEL NOT AVBL
FYWB	A0194/19	1905131508	1908131500 EST	MET HOURS OF SERVICE DAILY: 03H30-12H30 14H30-15H30 17H30-18H30
FYWB	A096/19	1905151045	1908311700	ILS/DME OPR BUT IN TEST MODE AND NOT TO BE USED FOR OPS.
FYWB	A0197/19	1905160600	1906071600	FIS TRAINING IN PROGRESS ON FREQ.122.5MHZ. PILOTS REQUESTED TO EXER PATIENCE DURING THIS PERIOD.
FYWB	A0198/19	1905160600	1906071600	TWR TRAINING IN PROGRESS ON FREQ.122.5MHZ. PILOTS REQUESTED TO EXER PATIENCE DURING THIS PERIOD.
FYWB	A0214/19	1905250838	1905250930	AD CLSD DUE TO FG

3

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.



**Namibia Civil Aviation Authority**  
**Air Navigation Service**  
**Aeronautical Information**  
**Management**

## Daily NOTAM Bulletin

Effective Date:  
15 Sep 2018

AIM SSI -001 F -03

Version 2

FYWE	A0479/18	1811281503	PERM	HAND AMEND NAMIBIA AIP AD FYWE AD 2-13 FYWE AD 2.22 FLIGHT PROCEDURES PARA. 2 DELETE EXISTING TEXT AND INSERT THE FOLLOWING TEXT: RNP APCH RWY 01 FOR NCAA APPROVED OPERATORS ONLY.
FYWE	A0489/18	1812031204	PERM	EROS AD METEOROLOGICAL OFFICE DOES NOT SEND A METAR AN HOUR PRIOR TO THE OPERATIONS OF THE AD.
FYWE	A0013/19	1901190400	PERM	HAND AMEND NAMIBIA AIP PAGE FYWE AD2-20 REVERSE OF VIS APP CHART TABLE WITH ENTRY AND EXIT ALT, LINE 4-HEJAL, DELETE THE WORDS OR BELOW UNDER EXIT ALT. LINE 3 TO READ HEJAL ENTRY ALT 7500FT, EXIT ALT 7000FT. INSERT NEW PARAGRAPH AFTER WAYPOINTS MUST BE SPOKEN AS FOLLOWS NOTE MODEL ACFT FLYING 900M EAST OF PSN HEJAL UP TO 150FT AGL. ALL ACFT MUST CROSS HEJAL MIN 7000FT AMSL.
FYWE	A0064/19	1903141600	1906131500	MET EQUIPMENT UNCALIBRATED DUE TO MET SERVICE PROVIDER NOT MEET ANNEX 3 REQUIREMENTS.
FYWE	A0187/19	1905082200	1907082200	ABN U/S
FYWH	A0058/18	1903051345	1906052359	ANNUAL WGS-84 SURVEY NOT COMPLETED. ALL AERODROME DATA NOT VALIDATED.
FYWH	A0055/19	1903012359	1905310400	THE APRON MARKINGS AT FYWH ARE NOT COMMENSURATED TO TRAFFIC THAT FYWH INTENDS TO SERVE, THEREFORE APRON MARKINGS MUST BE DISREGARDED. THE PILOTS MUST FOLLOW THE MARSHALLERS SIGNALS.
FYWH	A0063/19	1903141623	1906131500 EST	MET EQUIPMENT UNCALIBRATED DUE TO MET SERVICE PROVIDER NOT MEET ANNEX 3 REQUIREMENTS.
FYWH	A0149/19	1904151729	1907152030	AD HR OF OPS/SERVICE FOR HOSEA KUTAKO INTL. AP ARE AS FOLLOWS: MON, TUE, THU AND SAT 02H00-20H30 WED, FRI AND SUN 02H30-20H30
FYWH	A0115/19	1904050000	1906302359	FYWH ILS/DME WD FREQ 110.3MHZ RWY26 OPR BUT GND CK ONLY AWAITING FLT CK.
FYWH	A0154/19	1904180804	1907162030	PORTABLE AIRCRAFT MOORING WEIGHTS AVAILABLE. 3X35KG PAIRS 3X50KG PAIRS 3X70KG PAIRS THE KEY FOR THE MOBILE TROLLEY IS AVAILABLE FROM THE APRON OFFICE LOCATED AT THE FIRE STATION.

4

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.



**Namibia Civil Aviation Authority**  
**Air Navigation Service**  
**Aeronautical Information**  
**Management**

## Daily NOTAM Bulletin

Effective Date:  
15 Sep 2018

AIM SSI -001 F -03

Version 2

FYWH FIR	A0420/18	1810261434	PERM	HAND AMEND AIP AD FYLZ AD 2-6 FYLZ AD 2.17 ATS AIRSPACE 1. DESIGNATION AND LATERAL LIMITS AMEND ATZ TO CTR
FYWH FIR	A0453/18	1811160927	PERM	HAND AMEND AIP ENR 6.1-1 ROUTE UN185 UN183 FROM DUTPU TO EGRED SHOULD READ UN185
FYWH FIR	A0207/19	1905241515	1905250225	GOOGLE HIGH ALTITUDE UNMANNED FREE BALLOON IN THE FYWH FIR. PATH DEFINED BY THE FOLLOWING COORDINATES: ENTER 195447.36S01024.16E EXIT 17466.79S0185148.39E  F) GND G) FL540
FYWH FIR	A0461/18	1811210748	PERM	HAND AMEND NAMIBIA AIP FYWE AD 2-14 AD 2.23, 3 PARAGLIDING DELETE IN TOTO PARA 3.1 ENR 5.5-1 PARAGLIDING AREAS DELETE IN TOTO GROSS HERTZOG TWR AND ASSOCIATES TEXT.
FYWH FIR	A0060/19	1903121200	1905311500 EST	SPECIAL ADVISORY DUE TO RECENT ACFT ACCIDENTS OF THE BOEING 737 MAX 8 CLASS OF ACFT IN TERMS OF SECTION 47 OF THE NAMIBIA CIVIL AVIATION ACT, THE EXECUTIVE DIRECTOR PROHIBITS ALL B38M ACFT FROM ARRIVING OR DEPARTING FROM AERODROMES WITHIN FYWH FIR. THIS PROHIBITION SHALL REMAIN IN PLACE UNTIL SUCH TIMES AS RECOMMENDATIONS FROM THE ONGOING INVESTIGATIONS ARE MADE, OR OTHER INFORMATION BECOMES AVAILABLE FROM THE MANUFACTURER TO FURTHER ALLOW THE SAFE OPERATION OF THE ACFT TYPE.
FYWH FIR	A0107/19	1904021628	1905311700	VOLMET BROADCAST ON FREQ 126.8MHZ OUT OF SERVICE.
FYWH FIR	A0168/19	1905280600	1905301430	FYR133 ACTIVATED  F) GND G) FL145
FYWH FIR	A0205/19	1905200001	1906302359	AREA CONTROL CENTRE TRAINING TAKING PLACE ON 124.7MHZ
FYWH FIR	A0211/19	1905240600	1908311600	RPAS ACT 3NM SE OF FYAR IN THE ROSSING MINE AS DEFINED IN THE COORDINATES: 222733.01S 0150441.8E 222847.27S0150518.48E 223039.18S0150244.76E 222857.02S0150139.12E. ACFT TO CROSS THE PIT, STOCK PILE AND WASTE DUMP 3500FT AMSL OR ABOVE.  F) GND G) 3500FT AMSL

5

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.



**Namibia Civil Aviation Authority**  
**Air Navigation Service**  
**Aeronautical Information**  
**Management**

## Daily NOTAM Bulletin

Effective Date:  
 15 Sep 2018

AIM SSI -001 F -03

Version 2

FYWH FIR	A0212/19	1905310600	1905311430	FYR133 ACTIVATED  F) GND G) FL145
FYWH FIR	A0213/19	1905310600	1906031300	DAILY 0600-1300  LIVE FIRING EXERCISE WILL TAKE PLACE AT LUIPERD VALLEY SHOOTING RANGE WITH THE FOLLOWING COORDINATES: 223935S0170541E 224006S0170522E  F) GND      G) FL145

6

Please Note:

It is the responsibility of the operator to routinely monitor the DCA Website for the latest NOTAM bulletin update.