

Take Care **CLEANING** *And preflight properly.*

Application of polish over a static port can cause an inflight failure if the pilot fails to notice it in a pre-flight.

Prevention 1: Cleaning staff should be aware of the areas which require special care and where polish should not be applied.

Prevention 2: Care should always be taken to pre-flight properly including checking inside the pitot and static ports.



WWW.NCAA.COM.NA
SPQ@NCAA.COM.NA
083 235 2100

